




TOP VIEW
Plate Subassembly




SECTION A-A
SCALE 1 : 1



Assembly Instructions

- 1 Center label and instal on outside of enclosure's door.
- 2 Insert item 9, 4x mounting feet & screws in plastic bag, inside the enclosure and tape the bag on the bottom wall of the enclosure.
- 3 Use the screws that come with the plate and enclosure. Give to engineering extra pair of screws.



PROPRIETARY AND CONFIDENTIAL
The information contained in this drawing is the sole property of RKI Instruments. Any reproduction in part or as a whole without the written permission of RKI Instruments is prohibited.

| | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------|--------------------|------------------------------------------------------|--|----------------------------------------------------------------------|--|
| DO NOT SCALE DRAWING | | All Dimensions Are In Inches Unless Otherwise Noted. | | RKI Instruments, Inc. www.rkiinstruments.com | |
| Deburr | Break Edges .010 R | MATERIAL: SEE BOM | | TITLE: Power Supply in 4X Housing, 100-240 VAC in/24 VDC 4.5 Amp Out | |
| Tolerances & Finishes Unless Otherwise Noted: .XX ± .010 Angles ± 0° 30' .XXX ± .005 Conc. .010 TIR Fractions ± .015 Finish 128 | | FINISH: None | | B DRAWN BY: AP PART NUMBER: 49-0121-10 REVISION: P1 | |
| Finish for O-ring Grooves, 3 Sides 32 | | SCALE: 1:2 | | APPROVED BY: DATE: 07/19/21 PAGE 1 OF 1 | |