0	Release	4/24/00	
A	Changed MTL5401 to MTL5041	8/30/00	

Hazardous Area

Non-Hazardous Area

Beacon 800

Detector Wiring Typical







DO NOT SCALE DRAWING		All Dimensions In Inches Unless Otherwise Noted.	RKI Instruments, Inc. Hayward, CA 94544
Deburr	Break Edges .010 R		
Tolerances & Finishes Unless Otherwise Noted: .XX ± .010 Angles ± 0° 30' .XXX ± .005 Conc. .010 TIR Fractions ± .015 Finish 125		MATERIAL: N/A	TITLE: **Wiring, GD-K8AI to Beacon 800 w/MTL5041 Barrier**
Finish for O-ring Grooves, 3 Sides 32		FINISH: N/A	B | DRAWN BY: CM | PART NUMBER: **GD-K8AI-R02** | REVISION: A
		SCALE: N/A	APPROVED BY: | DATE: 4/24/00 | PAGE 1 OF 1