

GX-Force Troubleshooting Chart

Document No.GX-Force_SW501

Approval	Review	Preparation
Name: Engineering Div. 2 Mutou	Name: Engineering Div. 2 Hirao	Name: Engineering Div. 2 Ikarashi
Date 2021/10/1	Date 2021/10/1	Date 2021/9/30

No.	Date	Version	Revised content	Remarks
EX.	20XX/XX/XX	RevX.X	Create New	
1	2021/9/30	Rev1.0	Create New	
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				

Troubleshooting Chart (SW501)

No.	Incident date	Person in charge	Products	Occurrence Soft_Ver	Occurrence Phase	Failure detail	Priority	Status	Counter-measure date	Person in charge	Cause・Corrective action	Fixed Soft_Ver	Remarks
1	2021/8/26	Taki	GX-Force	20210524	Integration test	"FLOW" is displayed on the flow rate drop confirmation display screen when the pump is abnormal	A	Confirmed	2021/8/27	Ikarashi	Modified to display "PUMP" when the pump is abnormal.	20210827	
2	2021/9/6	Taki	GX-Force	20210524	Integration test	The letter "M", which means the memory number, is not displayed on the date and time display screen for browsing snap logs.	A	Confirmed	2021/9/7	Ikarashi	Fixed to display "M" just before the memory number.	20210907	